|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drinking water facilities in ward no:13. Shettyhalli

Address: Sub Division.

Location: 3rd cross Prashanth Nagara. **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 850 - 1050 **Yield :** 460 - 680 - 870

Casing Pipe Required : 51 - 55 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

For Samrudhi Ground Water Consultant

Smt. Kavitha Singh

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned with CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drinking water facilities in ward no. 13. Shettyhalli

Address: Sub Division.

Location: 8th cross kalyana Nagara. **Topography** Magnetic soil

Soil Type : Gravati Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 840 - 1070 **Yield :** 450 - 690 - 870

Casing Pipe Required : 51 - 57 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

For Samrudhi Ground Water Consultant

Smt. Kavitha Singh

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ

Scanned with CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drinking water facilities in ward no.13. Shettyhalli

Address: Sub Division.

Location: 17th Cross BHEL mini colony. **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 9"

Depth Recommended : 820 - 1090 **Yield :** 450 - 720 - 840

Casing Pipe Required : 50 - 56 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1

Remarks: Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with a good Knowledge and experience, However no guarantee of Water will be given

Samrudhi Ground Water Consultant
3rd M in Road, 3rd Cross
Swanthpur
BANGALORE - 560 022.
Mob.: 9964702826

Smt. Kavitha Singh

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ

Scanned with CamScanner